



Corrections of Hardware Manual

MB96300

MB96300_HWM_rev15_20080201-corr-x1-00

© Fujitsu Microelectronics Europe GmbH

Addendum, MB96300 Hardware Manual (MB96300_HWM_rev15_20080201)

This is the Addendum for the Hardware Manual MB96300_HWM_rev15_20080201 of the MB96300 microcontroller series. It describes all known discrepancies of the MB96300 microcontroller series Hardware Manual.

Ref. Number (Internal ref. number) (Text Link)	Date dd.mm.yy	Version No.	Chapter/Page	Description/Correction
HWM96300001	18.03.08	1.00	22.8.1	Wrong description for Interrupt register INTRn

CHAPTER 22 CAN CONTROLLER

22.8.1 Interrupt Register (INTRn)

Wrong description for Interrupt register INTRn

Current (wrong):

Address: Base + 0x08H ... INTRH

Address: Base + 0x09H ... INTRL

Correct:

Address: Base + 0x09 ... INTRHn

Address: Base + 0x08 ... INTRLn

(MWi/PKu/MHe)